



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Kathleen Clarke
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

INSPECTION REPORT

Partial: XXX Complete: Exploration:
Inspection Date & Time: 6/18/2001 / 10:00am-3:00pm
Date of Last Inspection: 6/18/2001

*PHL
by
JH*

Mine Name: Wellington Preparation Plant County: Carbon Permit Number:
Permittee and/or Operator's Name: Nevada Electric Investment Company (NEICO)
Business Address: c/o Mt. Nebo Scientific, P.O. Box 337, Springville, Utah 84663
Type of Mining Activity: Underground Surface Prep. Plant XXX Other
Company Official(s): Patrick Collins
State Official(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: 90's, Clear Skies
Existing Acreage: Permitted 1573.9 Disturbed 392 Regraded Seeded
Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 th Quarter- April, May, June)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/012

DATE OF INSPECTION: 7/20/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

No new amendments have been sent to the Division by the permittee.

2. SIGNS AND MARKERS

Spot-checks of the disturbed area markers were made throughout the property. The permittee was in compliance.

The identification signs were inspected at the main gates entering the property from the county roads. All information was correct and complied with the R645 Coal Rules.

The topsoil pile was identified as such and met the requirements of the R645 Coal Rules.

3. TOPSOIL

The topsoil pile was inspected and there were no signs of erosion. The topsoil pile is surrounded by a berm.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot-checked and were found to comply with the requirements of the Mining and Reclamation Plan and the R645 Coal Rules.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment ponds were not discharging during the inspection and are not likely to discharge in the near future. These ponds did contain a little or no water. There were no signs of any hazardous conditions during the inspection.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Siltation structures were inspected and complied the R645 Coal Rules. The permittee uses straw bales and silt fences in the disturbed area. However, the permittee was advised that a section of silt fence will need to be replaced in the near future. The silt fence has started to show signs of deterioration caused by the sun's rays. The location of the silt fence is at the Siaperas ditch. Several segments of this silt fence line have been replaced this summer.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/012

DATE OF INSPECTION: 7/20/2001

4D. HYDROLOGIC BALANCE: WATER MONITORING

The inspector reviewed the second quarter water monitoring prior to the inspection by using the Water Data System. It consisted of checking parameters and sampling the required water site. The permittee met the requirements in the R645 Coal Rules and the MRP. The permittee has submitted all information for second quarter into the water electronic database system. The second quarter water monitoring samples have been taken and are currently being analyzed by the lab. This information will be submitted to the Division by the end of the third quarter. The third water samples have not been taken at this time but will be completed by the end of the quarter.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

Refuse pile was inspected with no hazardous conditions being noticed. The slurry ponds were inspected weekly. No dust was seen during the inspection.

8. NONCOAL WASTE

The area was clear of non-coal waste material.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

No new support facilities were built since the last inspection.

Inspector's Signature: _____

Stephen J. Demczak #39

Date: July 31, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM
Patrick Collins, Mt. Nebo for NEICO
Price Field office

O:\007012.WEL\Compliance\2001\p_0720.wpd